

# XTREMA EB

## MAINTENANCE SCHEDULE



### DAILY CHECKLIST



1. Take the machine to a suitable waste disposal area.



2. Activate the handbrake.




3. Close the hopper door.



4. Turn off the vacuum system.



5. Clean the filter.



6. Raise the hopper to the required height (max. high dump height 1350mm).



7. Open the hopper door and empty out the dirt that has been collected.



8. Inspect and clean the brushes. Ensure that there is no string or wire wrapped around the brushes and that the bristles are intact.



9. Lower the hopper.



10. Check the battery's charge level and put on charge if necessary.



11. Once charging is complete, check the level of electrolytes in the battery and if necessary, add distilled water (only for lead acid batteries).




If any of these parts are worn or damaged, replace them or contact technical assistance.

### WEEKLY CHECKLIST



1. Inspect the dust skirts for wear or damage.



2. Check the condition of the main and side brushes. If necessary, adjust or replace them.



3. Check that the gaskets which seal the hopper are intact and in good condition.



4. Verify the integrity of the filter.



5. Check hydraulic oil level.